

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

Representatives Present During the Inspection:				
Company	Alden Gustefsen Permit Coordinator			
OGM	Joe Helfrich Environmental Scientist III			

Inspection Report

Permit Number:	C0070011
Inspection Type:	PARTIAL
Inspection Date:	Thursday, July 15, 2004
Start Date/Time:	7/15/2004 9:00:00 AM
End Date/Time:	7/15/2004 1:00:00 PM
Last Inspection:	Thursday, June 24, 2004

Inspector: Joe Helfrich, Environmental Scientist III

Weather: sunny windy 80
InspectionID Report Number: 333

Accepted by: whedberg

8/8/2004

Permitee: HIAWATHA COAL CO INC
Operator: HIAWATHA COAL CO INC
Site: HIAWATHA MINE COMPLEX

Address: PO BOX 1202, HUNTINGTON UT 84528

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Mineral Ownership Typ	es of Operations
-----------------------	------------------

_			_	
ſ	12,177.00	Total Permitted	✓ Federal	✓ Underground
Ī	290.00	Total Disturbed	☐ State	Surface
Ī		Phase I	☐ County	Loadout
Ì		Phase II	✓ Fee	Processing
Ì		Phase III	☐ Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

The purpose of this site visit was to conduct a partial inspection of the Hiawatha complex. There are no pending permit conditions or amendments and no compliance issues.

Inspector's Signature

Joe Helfrich, Environmental Scientist III

Date

Monday, July 19, 2004

Inspector ID Number: 1

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Vhere ideas connect

Permit Number: C0070011 Inspection Type: PARTIAL

Inspection Date: Thursday, July 15, 2004

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 b. For PARTIAL inspections check only the elements evaluated.
 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.

- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	~		\checkmark	
2.	Signs and Markers	V		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures	V		V	
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	Roads: Construction, Maintenance, Surfacing				
16.t	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070011 Inspection Type: PARTIAL

Inspection Date: Thursday, July 15, 2004

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The DOGM permit was issued on March 14, 2002 and expires on March 14, 2007.

2. Signs and Markers

Signs containing the required information were posted at access points to the property.

4.c Hydrologic Balance: Other Sediment Control Measures

The culverts at the RR crossing below the #1 slurry pond were inspected. One of the culverts could use some additional cleaning at both ends.

4.d Hydrologic Balance: Water Monitoring

Water monitoring for July includes field parameters for sites ST2 through ST5.